

# VEHICLE INSPECTION REPORT

**PJ20EDK**

## Fiat Ducato 35 2.3 Multijet 140PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 29/07/2020

VIN ZFA25000002N87326

CAP Below £4,600.00

Year 2020

Body Style Panel Van LWB

Gearbox MANUAL

Mileage 113,037 Miles  
Warranted

MOT Due 04/08/2025

Gears 6

Fuel Type Diesel

CAP Clean £6,275.00

Colour WHITE

CAP Average £5,600.00

SIDE LOADING DOOR, AD BLUE, E/MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Navigation system
- Park assist camera
- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Up To 25mm Thru Paint



2: Bonnet  
Chipped  
Multiple Chips



3: Screen Front  
Chipped  
Over 10mm



4: Bumper Front  
Dented  
2 Or Less UpTo 10mm



5: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



6: Wing nsf  
Scratched  
Over 25mm Thru Paint



7: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



8: Sill ns  
Dented  
With Paint Damage





9: Door nsf  
Dented  
With Paint Damage



10: B Post ns  
Chipped  
Multiple Chips



11: Door nsr  
Scratched  
Over 25mm Thru Paint



12: Door nsr  
Dented  
With Paint Damage



13: Sill ns  
Dented  
With Paint Damage



14: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm





15: Sill ns  
Dented  
With Paint Damage



16: Qtr Panel nsr  
Dented  
With Paint Damage



17: Lamp nsr  
Broken  
Replace



18: Qtr Panel Trim os  
Scuffed  
Over 25mm



19: Sill os  
Rusted  
Over 5mm



20: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

<b>Carpet Condition</b>	<b>Average</b>	<b>Upholstery Condition</b>	<b>Average</b>
<b>Seat Condition</b>	<b>Average</b>	<b>Odour</b>	<b>No</b>
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK