COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BK73ZFA

Ford Transit 350 2.0 EcoBlue 130ps

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45209
Cap Code	FOTR20331RBDTM2 5 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Average**	£12,150.00
Reg. date	09/02/2024	**VIN**	WF0AXXTTRAPS21800	**CAP Below**	£10,650.00
Year	2024	**Body Style**	Dropside L3	**Gearbox**	MANUAL
Mileage	60,197 Miles Not Warranted	**Service history**	None	**Gears**	6
Fuel Type	DIESEL	**MOT Due**	08/02/2027	**Tail Lift**	Column
GVW	3500kg	**CAP Clean**	£12,850.00		

NON-RUNNER, NO BRAKES AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features







- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Central locking

Photos











MyView
0
mph

HISTORY


60197.4 mls
Brake fluid
level low
OK



TRANSIT
BASE
2.0 I-PCR Panther Diesel
130 PS
Stage 6.2
350L
FORD
e1*2007/46*1096
WF0AXXTTRAPS21800
BKFB
0.50
3500 kg
5065 kg
1750 kg
2250 kg
W(mm)
L(mm)
a(mm)
J
3954
FED







BK73 ZFA







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Scratched
Over 25mm Not Thru Paint



3: Door nsf
Scratched
Over 25mm Not Thru Paint



4: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



5: Seat Base Cover nsf
Soiled
Heavy



6: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
Brakes	Fault		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK